


CERTIFICATE OF STABILITY OF STRUCTURE

1. PROPOSAL : SCHOOL BUILDING
2. REF. NO. : BUILDING AT ZAUTA,
3. NAME AND ADDRESS : TENDER CARE HOME,
OF THE OWNER : G.NO. 115(P) AT ZAUTA, A'BAD.
Ph. _____
4. NAME AND ADDRESS OF : SUNIL M. DESHPANDE, A'BAD.
ARCHITECT. Ph. 0240-2333183.

I hereby certify that the structural work of the above proposal has carried out as per my structural design and details and the said structure is safe and stable for the purpose for which it is intended.


(Signature of Structural Engineer)
Name and Registration No.)

Address :  **anil datar & associates**
STRUCTURAL DESIGNER & INDUSTRIAL CONSULTANTS
7A, N-1, Near St. Xavier - Highschool, CIDCO,
Aurangabad- 431003. Phone-2486294

APPENDIX -J

COMPLETION CERTIFICATE

June 27 2012

TO
THE SARPANCH/SECRETARY
GRAMPANCHAYAT, ZALTA
AURANGABAD

DERA SIR,

I HERE BY CERTIFY THAT FULL DEVELOPMENT WORK OF SCHOOL BUILDING ON GUT NO. 115 (P), AT ZALTA, TAL & DIST AURANGABAD HAS BEEN SUPERVISED BY ME AND HAS BEEN COMPLETED ON DATED 05.06.2012 ACCORDING TO PLAN SANCTIONED BY LOCAL AUTHORITY VIDE OFFICE COMMUNICATION NO. DATED THE WORK HAS BEEN COMPLETED TO MY BEST SATISFACTION THE WORKMANSHIP AND ALL THE MATERIAL (TYPE AND GRADE) HAVE BEEN USED IN STRICTLY IN ACCORDANCE WITH GENERAL AND DETAILED SPECIFICATIONS. NO PROVISION OF THE ACT OR THE BUILDING BYLAWS, ANY REQUISITIONS MADE, CONDITION PRESCRIBED OR ORDER ISSUED THEREUNDER HAS BEEN TRANSGRESSED IN COURSE OF THE WORK. I AM ENCLOSING THE COPY OF THE WORK DONE PLANS. THE BUILDING IS FIT FOR OCCUPANCY FOR WHICH IT HAS BEEN CONSTRUCTED.

I HAVE TO REQUEST YOU TO ARRANGE FOR THE INSPECTION AND GIVE PERMISSION FOR THE OCCUPATION OF THE BUILDING.

SUNIL M. DESHPANDE
ARCHITECT